




# PRODUCT OBSOLESCENCE MEMO

## SINGLFUSE™ SMD FUSES



## Bourns® Model SF-1210SxxxW Series to be Discontinued

Riverside, California – April 8, 2021 – In accordance with our ongoing product life cycle management, Bourns will be discontinuing the SinglFuse™ SMD Fuse Model SF-1210SxxxW series. Diminishing demand necessitates this action. The discontinued part numbers and their recommended replacement part numbers can be found in the table below.

Obsolete Part Numbers	Replacement Part Numbers
<a href="#">SF-1210S100W-2</a>	<a href="#">SF-1206S100M-2</a>
<a href="#">SF-1210S150W-2</a>	<a href="#">SF-1206S150W-2</a>
<a href="#">SF-1210S200W-2</a>	<a href="#">SF-1206S200W-2</a>
<a href="#">SF-1210S250W-2</a>	<a href="#">SF-1206S250W-2</a>
<a href="#">SF-1210S300W-2</a>	<a href="#">SF-1206S300W-2</a>

Customers must notify Bourns in writing within 30 days of publication of this notification if they consider the discontinued product to be sole sourced by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate End of Product Life purchase for the discontinued products. Orders for these discontinued products during this End of Product Life transition period will be considered non-cancellable. Products purchased during this End of Product Life transition period will be considered non-returnable but will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **September 25, 2021**

Last time ship date: **December 18, 2021**

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

SF2106